Category 3: Excellence in Sustainability

Great Ocean Road Pavement Rehabilitation

Thomas Gauci Downer EDI Works



2021 AustStab Awards of Excellence



Overview

- Pavement Rehabilitation of 1.9km of Great Ocean Road
- Original Scope → No in situ stabilisation works
- Poor quality lower subgrade material identified
- 2% GB Cement Stabilisation undertaken
- Conforming subgrade compaction results achieved
- Granular Pavement Layers able to be constructed above



Geographic Location of Works






Overview

- The works were taking place almost directly adjacent to the entrance to the 12 Apostles Visitor Centre
- Original Scope of pavement works required Downer to construct 1.5 x 0.2m widening trenches on both sides of the pavement for the entire length of the road
- The widening trench material and existing subgrade material would all then be mechanically mixed to a depth of 200mm and then regulated to achieve a consistent height of 150mm below FSL
- We mechanically mixed, compacted and shaped the pavement across two days (28th and 29th January), only to return the following week to see the pavement had deteriorated significantly over the weekend whilst it was open to traffic
- Further investigation through the use of DCP testing revealed that the lower subgrade was
 of a very poor quality and did not possess the strength properties required for us to reach
 the required compaction
- The proposal Downer then provided to VicRoads was to supply and place a nominal 50mm layer of Class 3 FCR over the existing subgrade material and then stabilise the subgrade with 2% Cement to a depth of 250mm to try and bridge the lower strength lying issues
- The proposal was submitted on Thursday 4th February, approved on Friday 5th February, and works commencing on Monday 8th February



Outline of Initiative





Operating Environment

- Environmentally Sensitive Area
- Culturally Significant Area
- Tourist Hotspot
- Experiences both extremes of weather systems
- Proximity of site to construction resources
- Working under lane closures



Twelve Apostles turn-off 1km (working in tourist area)





Operating Environment

- At the commencement of the project, the cultural significance of the area was highlighted by the fact that Downer was required to abide by the Regional Road Victoria Contingency Arrangements for Discovery of Human Skeletal Remains, Historic Heritage or Aboriginal Cultural Heritage
- The contract also required Downer to engage a qualified ecologist to determine the extent of native vegetation to be protected on site
- This required No Go Zone fencing to be installed along the boundary between the road reserve and the native vegetation
- This equated to approximately 4km of No Go Zone fencing
- As works on this project were taking place over the Christmas period, significant restrictions to working hours and length of work sites were enforced
- More than 3 weeks of adverse weather days were incurred on this contract the consistent presence of rain made it even more crucial that the lower subgrade was exposed for the least amount of time



Key Challenges

- COVID 19 Regional border restrictions in Victoria
- Close proximity of waterways
- Presence of native/protected flora & fauna
- Working with live traffic
- Keeping the road open to traffic at all times
- Demonstration of the value of the initiative to client



No Go Zone fencing installed





Key Challenges

- Based on experience of previous contracts delivered in the area, VicRoads do not typically incorporate any form of stabilising in their pavement designs
- The primary concern of VicRoads when introducing stabilising was the potential for fatigue cracking due to having an extremely rigid/bound upper pavement layer sitting on a flexible lower subgrade
- Given the location of the works area, high daily traffic volumes and the social/media interest in the project, VicRoads requested all measures be taken to keep the road open and trafficable



Points of Interest

- Initial Client position → Subgrade rectification a contractual responsibility of Downer
- Client not traditionally receptive to Pavement Recycling techniques
- Client raised concerns regarding Fatigue Cracking

Initiative Testimonials

"Poor performing lower subgrade results will affect our ability to get compaction and also compromise the integrity of the finished product."

(Matt Billings, Downer Stabilisation Manager VIC/TAS)

"Big part of the problem will at 600 – 700mm depth, our previous experience suggests this is an issue that will keep reflecting through upper layers of pavement."

(Tony Egan, Downer Construction Manager VIC/TAS)



Evidence of Success

Sample Number	12373-35	12373-36	12373-37	12373-38	12373-39	12373-40
Location	DCP-01	DCP-02	DCP-03	DCP-04	DCP-05	DCP-06
Chainage (m)	269.140	269.263	269.460	269.600	270.044	270.268
Location Offset (m)	2.5m Left	1.8m Left	3.0m Right	4.0m Right	0.5m Left	2.0m Left
Offset from	CL	CL	CL	CL	CL	CL
Date Tested	02/02/2021	02/02/2021	02/02/2021	02/02/2021	02/02/2021	02/02/2021
Soil Description	Silty SAND	Silty SAND	Silty SAND	Silty SAND	Silty SAND	Silty SAND
Reduced Level (mm)	N/A	N/A	N/A	N/A	N/A	N/A
Moisture Condition	Moist	Moist	Moist	Moist	Moist	Moist
Start Depth (mm)	-200mm Subbase	-200mm Subbase	-200mm Subbase	-200mm Subbase	0.0	0.0
0-100 blows/100 mm	4	6	2	5	8	4
100-200 blows/100 mm	4	8	4	3	16	11
200-300 blows/100 mm	7	13	9	3	19	15
300-400 blows/100 mm	6	10	7	1	11	13
400-500 blows/100 mm	9	6	4	2	10	5
500-600 blows/100 mm	8	5	7	1	15	8
600-700 blows/100 mm	7	3	3	1	23	5
700-800 blows/100 mm	7	4	2	3	13	4
800-900 blows/100 mm	7	7	2	2	10	3
900-1000 blows/100 mm						
Ground Water Level						
Remarks						

DCP results prior to stabilisation works demonstrate poor CBR of in situ material

Density Ratio with factor %	99.0	96.5	99.0	99.5	96.5	96.0
Density Decay Factor	0.981	0.973	0.973	0.981	0.973	0.973
Compaction Method	Modified	Modified	Modified	Modified	Modified	Modified
Density Ratio %	101.0	99.0	102.0	101.5	99.0	99.0
Moisture Ratio %	87.0	71.0	85.5	84.5	88.5	88.5
Moisture Variation %	1.0	3.0	1.5	1.5	1.5	1.0
Adjusted Optimum Moisture Content (OMC) %						
Optimum Moisture Content (OMC) %	9.5	10.5	9.5	9.5	13.0	10.5
Adjusted Maximum Dry Density t/m3						••
Maximum Dry Density t/m3	2.10	2.12	2.03	2.06	1.93	2.16
Field Dry Density t/m ³	2.11	2.10	2.07	2.10	1.91	2.13
Field Moisture Content %	8.1	7.5	8.2	8.2	11.7	9.4
Field Wet Density t/m ³	2.28	2.26	2.24	2.27	2.13	2.33
Fraction Tested (mm)	19.0	19.0	19.0	19.0	19.0	19.0
Test Depth (mm)	225	225	225	225	225	225
Soil Description	Existing Limestone + CL2, 20mm CR (2% GB Cement)	Existing Limestone + CL2, 20mm C (2% GB Cement)				
Thickness of Layer (mm)	250	250	250	250	250	250
Layer / Reduced Level	Subbase	Subbase	Subbase	Subbase	Subbase	Subbase
Elevation (m)	N/A	N/A	N/A	N/A	N/A	N/A
Location Offset (m)	-2.4 from CL	2.4 from CL	1.6 from CL	0.0 from CL	4.0 from CL	3.2 from CL
Chainage (m)	269700.6	269756.0	269811.6	269867.0	269922.6	269978.0
Test Request #/Location	Great Ocean Road, Princetown	Great Ocean Road, Princetown				
Time Tested	18:05	17:50	17:41	17:32	17:23	17:15
Date Tested	10/02/2021	10/02/2021	10/02/2021	10/02/2021	10/02/2021	10/02/2021
Sample Number	12373-53	12373-54	12373-55	12373-56	12373-57	12373-58

Compaction results post stabilisation works demonstrate improved strength of in situ material

- The lower subgrade layer was required to comply with Section 304.08 of the VicRoads specifications
- Section 304.08 called for a Characteristic Density Ratio of not less than 97.0% for a max lot size of 4000m²
- Given that the area was stabilised equated to approximately 16000m², there were four 6 Lot Test undertaken
- Each of the compaction results post stabilisation achieved the required Characteristic Density Ratio



Supporting Data

1.0	Stabilisation of In-Situ Material Vs. Remove and Replace Failing Subgrade								
ltem	Description of Work	Estimated Quantity	Unit	Rate (\$)	Extended Amount (\$)				
1.1	Stabilise the pulverised layer and widening trench material with 2% GB cement to a depth of 250mm and width of 9.4 metres	16,074	m²	\$8.39	\$134,860.86				
1.2	Excavate, remove and dispose failed existing pavement material to a depth of 300mm and supply, place and compact size 20 class 2 FCR.	4823	m³	\$98.90	\$476,915.58				

Cost Analysis

 Cost Analysis highlights saving through Pavement Recycling

Clear Value Proposition presented to Client

Time/Production Analysis

	1.0	Stabilisation of In-Situ Material Vs. Remove and Replace Failing Subgrade						
	Item	Description of Work	Estimated Production	Unit	Actual Area to Treat	Duration of Works		
	1.1	Stabilise the pulverised layer and widening trench material with 2% GB cement to a depth of 250mm and width of 9.4 metres	4000m ²	Day	16074m²	4 days		
×	1.2	Excavate, remove and dispose failed existing pavement material to a depth of 300mm and supply, place and compact size 20 class 2 FCR.	320m³	Day	4823m ³	15 days		

- Significant time saving through Pavement Recycling
- Less disruption to Tourists and Local Residents





Supporting Data

- As evidenced through the Cost Analysis, the option to stabilise the pavement was more cost effective than removing the existing material and replacing it with virgin material
- The rate of \$98.90 for removal and replacement of unsuitable material was included as a Provisional Quantity Item in the schedule for this contract
- The rate of \$8.39 for Cement Stabilising was provided as a variation on request from VicRoads
- Both of these options were provided to VicRoads for consideration prior to the works being completed
- The productivity of both the stabilising and remove and replace options were calculated based on previous experience when completed similar works
- The combination of the time and cost saving demonstrated a clear value proposition for the initiative
- This allowed VicRoads to approve the works in a timely manner
- This was also a positive from a sustainability perspective as we did not have to replace the existing material with virgin quarry material in order to achieve the desired outcome





Practical Application

6	Pulverize Existing Seal and Shape Existing (Ch.269000 to Ch.269810)	Wed 27 Jan '21	Thu 28 Jan '21	2 days	37SS,35
7	Rip, Mix & Spread Existing (Ch.269810 to Ch.270710)	Wed 27 Jan '21	Thu 28 Jan '21	2 days	35
88	Earthworks box out (Ch.269000 to Ch.269810 Both Sides)	Fri 29 Jan '21	Mon 1 Feb '21	2 days	36
39	Place Regulating Layer/Shape to 150mm below FSL /Shape to 150mm below FSL (Ch.269000 to Ch.269810)	Tue 2 Feb '21	Fri 5 Feb '21	4 days	38
10	Place 50mm Class 3 Layer for Stabilizing (Ch.269000 to Ch.270710)	Mon 8 Feb '21	Tue 9 Feb '21	2 days	39
11	2% Cement Stabilisation of Subgrade Layer (Ch.269000 to Ch.270710)	Tue 9 Feb '21	Fri 12 Feb '21	4 days	40SS+1 day

Excerpt of Great Ocean Road Construction Program

- Princetown Mean Rain Days (Feb) = 9.1 days
- Princetown Mean Rainfall (Feb) = 40.2mm
- ✤ Time savings through Stabilising initiative → Less Risk with leaving poor subgrade open to adverse weather
- AADT refers to Annual Average Daily Traffic
- This value is denoted in the VicRoads specification
- Based on actual time taken to complete the stabilising works, approximately 7,200 vehicles were affected during the works
- The fact that the initiative took approximately a third of the time to complete in comparison to the remove and replace option meant that no road closures were required and overall safety of the area was improved

- ightarrow Actual time taken ightarrow Aligns with estimate
- AADT of Great Ocean Rd is 1800 Vehicles
- No. of Vehicles affected <u>during initiative</u> → 4 days x 1800 Vehicles = 7,200 Vehicles
- ❖ Vehicles affected without Pavement Recycling → 15 days x 1800 Vehicles = 27,000 Vehicles
- Produced safe trafficable surface
- No Road Closures or Safety Incidents

		OCEAN RD. PRINCETOWN - PAVEMENT REHABILITATION				CONTRACT NUM	1050, 44423
EOT CLAIM #	DATE	CCEAN RD, PRINCE TOWN - PAVEMENT REHABILITATION REASON FOR EXTENSION OF TIME CLAIM	TIME CLAIMED	REPLY DATE	DATE APPROVED	AMMEND CONT COMPLETION DATE	NOTES
1	11/11/2020	Adverse weather at Great Ocean Rd, Princetown on Wednesday 11th of November 2020.	0 days		-	10/03/2021	Adverse weather da 1/10
2	15/01/2021	Adverse weather at Great Ocean Rd, Princetown on Friday 15 th of January 2021.	0 days		-	10/03/2021	Adverse weather da 2/10
3	29/01/2021	Adverse weather at Great Ocean Rd, Princetown on Friday 29th of January 2021.	0 days		-	10/03/2021	Adverse weather da 3/10
4	19/04/2021	Adverse weather at Great Ocean Rd, Princetown on Monday 19th of April 2021. Works could not continue on preparation of pavement for seal.	0 days		17/05/2021	12/05/2021	Adverse weather da 4/10
5	20/04/2021	Adverse weather at Great Ocean Rd, Princetown on Tuesday 20th of April 2021. Works could not continue on preparation of pavement for seal	0 days		17/05/2021	12/05/2021	Adverse weather da 5/10

Excerpt of Extension of Time Register



Supporting Visual Content



DCP testing on lower subgrade layer



Struggling to keep the subgrade trafficable



First run of cement stabilising completed



The Team delivering a quality result





Compaction effort on treated subgrade layer



Proof roll of subgrade layer and ITP sign-off with VicRoads